
DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453

(707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-010128 Address: 333 Burma Road **Date Inspected:** 25-Oct-2009

City: Oakland, CA 94607

Project Name: SAS Superstructure **OSM Arrival Time:** 700 **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes Li Ming, Gong Liang Zhu No **Inspected CWI report:** Yes No **Rod Oven in Use:** Yes N/A No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes N/A **Delayed / Cancelled:** No

Tower **Bridge No:** 34-0006 **Component:**

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance (QA) Inspector Umesh Gaikwad was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

Bay 11 Strut

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15%, Ultrasonic Testing (UT) of approximately 10% and random Visual Testing (VT) of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT and UT reports for this date. The members are identified as Tower Components. The weld designations reviewed are as follows.

WD1-A6001-4

Outside Yard South Tower Lift 3

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15% and random Visual Testing (VT) of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT reports for this date. The members are identified as Fit Lug on skin A, B, E of 85.25M & 92.5M diaphragm and skin A/B/E with diaphragm of 85.25M & 92.5M diaphragm. The weld designations reviewed are as follows.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

SSTL3-1B/K-35, 36, 39, 40

SSTL3-1B/K-23, 24, 25, 26

SSTL3-1B/K-51, 52, 73, 74

SSTL3-1B/K-42, 48, 49, 50

SSTL3-1F/K-31, 32, 37, 38

SSTL3-1F/K-23, 24, 25, 26

SSTL3-1F/K-51, 52, 53, 54


SSTL3-1F/K-35, 36, 29, 30, 49, 50

SSTL3-1B/K-41 (12mm MT LINEAR INDICATION OBSERVED)

SSTL3-1B/K-47 (15mm & 25mm MT LINEAR INDICATIONS OBSERVED)


During random verification Magnetic Particle Testing (MT) of South tower lift 3, 85.25M diaphragm to skin A, weld SSTL3-1B/K-41 and 85.25M to skin B, weld SSTL3-1B/K-47 located in the outside yard (near Milling section), Caltrans Quality Assurance (QA) Inspector discovered linear indications of approximately 12mm, 15mm and 25mm in length. This area had been previously tested and accepted by ZPMC NDT personnel (NDT Inspection Notification sheet # 004476). The attached photographs provide additional detail.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.










WELDING INSPECTION REPORT

(Continued Page 3 of 3)





Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Serge Sinevod 134-8257-0045, who represents the Office of Structural Materials for your project.

Inspected By:	Gaikwad,Umesh	Quality Assurance Inspector
Reviewed By:	Clifford,William	QA Reviewer